

L663 - Defender 2023
 Vehicle scanned on 13-09-2024 5:51 PM
 Using IIDTool BT V4.0 B0098-83

AAM-Audio Amplifier Module

Newer than reflash database

Part	Part number		Part number
Assembly (F112)	Unknown	->	N8B2-18C808-CAC
ID:	17A4		
IP:	169.254.243.195		
Assembly (F113)	N8E2-19C164-HB	->	None
Calibration (F124)	N8B2-14C527-CC	->	N8B2-14C527-CB
Calibration (F125)	N8B2-14C527-CAC		Up-to-date
Calibration (F126)	N8B2-14C527-ZA		Up-to-date
Hardware (F111)	M8E2-14C524-CA		
Serial	0398029		
Strategy (F188)	N8E2-14C526-HB		Up-to-date
VIN	SALEA*****		

ABS-Anti-Lock Brake System Control Module

Newer than reflash database

Part	Part number		Part number
Assembly (F112)	Unknown	->	N8B2-2C405-MZE

Assembly (F113)	P8B2-2D522-AD	->	None
Calibration (F124)	P8B2-14C037-MZE	->	N8B2-14C037-MZE
Hardware (F111)	PY42-14C227-AA		
Serial	342200073809		
Strategy (F188)	N8B2-14C036-AE	->	N8B2-14C036-AD
VIN	SALEA*****		

BCM-Body Control Module

Latest Version

Part	Part number
Assembly (F112)	Unknown
Assembly (F113)	M8E2-14F041-BA
Calibration (F124)	L8B2-14C185-AL
Hardware (F111)	M8E2-14C256-BA
Serial	4495311653
Signal (F108)	L8B2-14C408-AP
Strategy (F188)	L8B2-14C184-AP
VIN	SALEA*****

CCM-Cruise Control Module

Latest Version

Part	Part number
Assembly (F112)	Unknown
Assembly (F113)	M8B2-9G768-AD
Hardware (F111)	M8B2-14D047-AA

Serial	22-08-01-3546
Strategy (F188)	M8B2-14D049-AD
VIN	SALEA*****

CHCM-Chassis Control Module

Newer than reflash database

Part	Part number		Part number
Assembly (F112)	Unknown	->	L8B2-14E090-KAS
Assembly (F113)	M9R3-14F392-KA	->	None
Calibration (F124)	M8B2-14E094-KHF	->	L8B2-14E094-KAN
Calibration F121	L8B2-14E096-SA		
Hardware (F111)	M9R3-14E099-KA		
Serial	0000000026863269		
Signal (F120)	L8B2-14E093-SB		Up-to-date
Strategy (F188)	L8B2-14E093-KR	->	L8B2-14E093-KP
VIN	SALEA*****		

DADC-Driver Assistance Domain Controller

Newer than reflash database

Part	Part number		Part number
Assembly (F112)	Unknown	->	N8B2-14E140-AE
ID:	1416		
IP:	169.254.155.228		

Assembly (F113)	N9D3-14E159-AG	->	None
Calibration (F124)	N8B2-14E157-AG	->	N8B2-14E157-AE
Hardware (F111)	M9D3-14E158-AA		
Serial	5325805432208132		
Strategy (F188)	N9D3-14E153-AG	->	N9D3-14E153-AF
VIN	SALEA*****		

DDCM-Driveline Disconnect Control Module

Latest Version

Part	Part number
Assembly (F112)	Unknown
Assembly (F113)	M8E2-4C185-AC
Calibration (F124)	M8E2-4C180-AF
Hardware (F111)	M8E2-4C184-AC
Serial	223430028
Strategy (F188)	M8E2-4C179-AF

DDM-Driver Front Door Module

Newer than reflash database

Part	Part number		Part number
Assembly (F112)	Unknown	->	N8B2-14B531-AD
Assembly (F113)	M8E2-14D618-CA	->	None
Calibration (F124)	N8B2-14C065-AD	->	N8B2-14C065-AC

Hardware (F111)	M8E2-14C235-CA		
Serial	YM007VG602504000		
Strategy (F188)	M8E2-14C064-AH	->	M8E2-14C064-AG
VIN	SALEA*****		

DRDM-Driver Rear Door Module

Newer than reflash database

Part	Part number		Part number
Assembly (F112)	Unknown	->	N8B2-14B532-AD
Assembly (F113)	M8E2-14D620-CA	->	None
Calibration (F124)	N8B2-14C069-AD	->	N8B2-14C069-AC
Hardware (F111)	M8E2-14C236-CA		
Serial	YM007VG711532000		
Strategy (F188)	M8E2-14C068-AH	->	M8E2-14C068-AG
VIN	SALEA*****		

DSM-Driver Front Seat Module

Update available (ECU Flash Supported)

Part	Part number		Part number
Assembly (F112)	Unknown	->	N8B2-14C708-BE
Assembly (F113)	M8E2-14D600-AC	->	None
Calibration (F124)	N8B2-14C034-BF	->	N8B2-14C034-BE

Hardware (F111)	M8E2-14C249-AB		
Serial	22071401106		
Strategy (F188)	M8E2-14C030-BC	->	N9X2-14C030-AC
VIN	SALEA*****		

GSM-Gear Shift Module

No assembly exists

Part	Part number
Assembly (F113)	N8B2-7E453-BA
Hardware (F111)	N8B2-14C559-BA
Serial	91879VGC01936
Strategy (F188)	N8B2-14C561-AA
VIN	SALEA*****

GWM-Gateway Module 'A'

Update available (ECU Flash Support Unknown)

Part	Part number		Part number
ID:	1716		
IP:	169.254.139.4		
Assembly (F113)	M8E2-14F041-BA	->	M8E2-14F642-EF
Calibration (F124)	M8E2-14F531-CD	->	M8E2-14F531-CF
Hardware (F111)	M8E2-14C256-BA		
Serial	4495311653		
Strategy (F122)	M8E2-14F529-AB		Up-to-date

Strategy (F188)	M8E2-14F530-CD	->	M8E2-14F530-CE
VIN	SALEA*****		

HCMB-Headlamp Control Module 'B'

Newer than reflash database

Part	Part number		Part number
Assembly (F113)	L8B2-13E005-BB	->	P8A2-14F448-AA
Calibration (F124)	P8B2-14C085-BC	->	P8A2-14C085-BA
Hardware (F111)	J8A2-14C243-BC		
Serial	0380		
Signal (F108)	L8B2-14C399-BH		Up-to-date
Strategy (F188)	L8B2-14C084-BL		Up-to-date
VIN	SALEA*****		

HCM-Headlamp Control Module 'A'

Update available (ECU Flash Support Unknown)

Part	Part number		Part number
Assembly (F113)	L8B2-13E005-BB	->	P8A2-13K031-AA
Calibration (F124)	P8B2-14C085-AC	->	PK83-14C085-AA
Hardware (F111)	J8A2-14C243-BC		
Serial	0183		
Signal (F108)	L8B2-14C399-AH		Up-to-date
Strategy (F188)	L8B2-14C084-AL		Up-to-date

VIN	SALEA*****		
-----	------------	--	--

HVAC-HVAC Control Module

Newer than reflash database

Part	Part number		Part number
Assembly (F112)	Unknown	->	L8B2-18C612-BV
Calibration (F124)	P8B2-18D620-BC	->	L8B2-18D620-BU
Hardware (F111)	N8B2-14C239-BA		
Serial	220519380901		
Strategy (F188)	MK72-18D619-JA	->	MK72-18D619-FA
VIN	SALEA*****		

ICCM-Infotainment Compute Control Module

Newer than reflash database

Part	Part number		Part number
ID:	14B4		
IP:	169.254.52.149		
Assembly (F112)	L8B2-19L318-JZ	->	L8B2-19L310-JZ
Assembly (F113)	L8B2-19L300-JZ	->	None
Hardware (F111)	L8B2-19L317-JG		
Serial	207VIWPD57353		
Strategy (F188)	N8B2-19L312-BB	->	L8B2-19L312-BX
VIN	SALEA*****		

IGM-Infotainment Gateway Module

Newer than reflash database

Part	Part number		Part number
Assembly (F112)	L8B2-19L328-JZ	->	L8B2-19L320-JZ
Assembly (F113)	L8B2-19L300-JZ	->	None
Calibration (F125)	L8B2-19L326-01	->	None
Calibration F123	L8B2-19L329-01		
Hardware (F111)	L8B2-19L327-JG		
Serial	207VIWPD57353		
Strategy (F188)	N8B2-19L322-BB	->	L8B2-19L322-BX
VIN	SALEA*****		

IPCB-Instrument Panel Cluster Control Module 'B'

No assembly exists

Part	Part number
ID:	14B2
IP:	169.254.175.243
Assembly (F113)	P8B2-10F948-JB
Calibration (F124)	P8B2-10F943-AF
Calibration F121	P8B2-10F942-CB
Calibration F123	P8B2-10F942-EB
Hardware (F111)	P8B2-10F947-JA
Serial	JAGW025000

Signal (F120)	P8B2-10F942-BB
Strategy (F122)	P8B2-10F942-FB
Strategy (F188)	P8B2-10F942-AD
VIN	SALEA*****

IPMA-Image Processing Module 'A'

Latest Version

Part	Part number
Assembly (F112)	Unknown
ID:	1706
IP:	169.254.12.203
Assembly (F113)	N8B2-14F404-AC
Calibration (F124)	N8B2-14F398-AC
Hardware (F111)	M8E2-14F395-AA
Serial	2022081600001905
Signal (F120)	N8B2-14F397-BC
Strategy (F122)	00000000000000
Strategy (F188)	N8B2-14F397-AC
VIN	SALEA*****

NFSM-Near Field Sensing Module

Update available (ECU Flash Support Unknown)

Part	Part number		Part number
Assembly (F112)	Unknown	->	N8B2-19J240-GF
Strategy (F121)	Unknown	->	M8E2-19J243-GG
ID:	1434		

IP:	169.254.241.116		
Assembly (F113)	M8E2-19J249-AJ	->	None
Calibration (F124)	N8B2-19J244-BH	->	N8B2-19J244-HF
Calibration F121	M8E2-19J243-GH		
Hardware (F111)	M8A2-19J241-BE		
Serial	15AUG220025253F0		
Signal (F120)	M8E2-19J243-FH	->	M8E2-19J243-FG
Strategy (F188)	M8E2-19J243-EH	->	M8E2-19J243-EG

PCM-Powertrain Control Module

Latest Version

Part	Part number
Assembly (F112)	Unknown
Calibration (F124)	0DDP8B214C570BGB
Hardware (F111)	M8A2-14C568-CA
Serial	1674021822062217
Strategy (F188)	P8B2-14C570-BGB
VIN	SALEA*****

PDM-Passenger Front Door Module

Newer than reflash database

Part	Part number		Part number
Assembly (F112)	Unknown	->	N8B2-14B533-AD

Assembly (F113)	M8E2-14D617-CA	->	None
Calibration (F124)	N8B2-14C109-AD	->	N8B2-14C109-AC
Hardware (F111)	M8E2-14C237-CA		
Serial	YM007VG700918000		
Strategy (F188)	M8E2-14C108-AH	->	M8E2-14C108-AG
VIN	SALEA*****		

PRDM-Passenger Rear Door Module

Newer than reflash database

Part	Part number		Part number
Assembly (F112)	Unknown	->	N8B2-14B534-AD
Assembly (F113)	M8E2-14D619-CA	->	None
Calibration (F124)	N8B2-14C113-AD	->	N8B2-14C113-AC
Hardware (F111)	M8E2-14C238-CA		
Serial	YM007VG725301000		
Strategy (F188)	M8E2-14C112-AH	->	M8E2-14C112-AG
VIN	SALEA*****		

PSCMB-Power Steering Control Module 'B'

No assembly exists

Part	Part number
Assembly (F113)	M8B2-14F499-AD

Calibration (F126)	M8B2-14C609-DD
Hardware (F111)	M8B2-14F075-AA
Signal (F120)	M8B2-14C217-BD

PSCM-Power Steering Control Module

Latest Version

Part	Part number
Assembly (F112)	Unknown
Assembly (F113)	M8B2-14F499-AD
Calibration (F124)	M8B2-14C609-CD
Calibration (F125)	M8B2-14C218-CD
Hardware (F111)	M8B2-14F075-AA
Serial	00517156
Signal (F108)	M8B2-14C386-AB
Strategy (F188)	M8B2-14C217-AD
VIN	SALEA*****

PSM-Passenger Front Seat Module

Update available (ECU Flash Supported)

Part	Part number		Part number
Assembly (F112)	Unknown	->	N8B2-14F316-BE
Assembly (F113)	M8E2-14D600-AC	->	None
Calibration (F124)	N8B2-14C034-BF	->	N8B2-14C034-BE
Hardware (F111)	M8E2-14C249-AB		

Serial	22071401368		
Strategy (F188)	M8E2-14C030-BC	->	N9X2-14C030-AC
VIN	SALEA*****		

RCM-Restraints Control Module

Latest Version

Part	Part number
Assembly (F113)	M9V2-14D374-AB
Calibration (F124)	P8B2-14C098-AA
Calibration (F126)	M9V2-14C098-AA
Hardware (F111)	M9V2-14C246-AA
Serial	W224CeA3778
Strategy (F188)	M9V2-14C028-AB
VIN	SALEA*****

RFA-Remote Function Actuator

Newer than reflash database

Part	Part number		Part number
Assembly (F112)	Unknown	->	M9A3-19G481-BT
Assembly (F113)	M9R3-19H440-BD	->	None
Calibration (F124)	L8B2-14C105-DH	->	M9A3-14C105-BF
Hardware (F111)	M9R3-14C250-BD		
KVM State	Locked Forever		
Serial	589415664022236		

Signal (F108)	L8B2-14C430-AD		Up-to-date
Strategy (F188)	L8B2-14C104-AP	->	L8B2-14C104-AN
VIN	SALEA*****		

RHVAC-Rear HVAC Control Module

Latest Version

Part	Part number
Assembly (F112)	Unknown
Calibration (F124)	L8B2-14F218-AB
Hardware (F111)	HY32-14F215-NB
Serial	220505016401
Signal (F108)	L8B2-14F216-BA
Strategy (F188)	L8B2-14F217-BD
VIN	SALEA*****

SASM-Steering Angle Sensor Module

Latest Version

Part	Part number
Assembly (F112)	Unknown
Assembly (F113)	M8B2-3F818-AA
Hardware (F111)	M8B2-14F077-AA
Serial	22MAR190042AAJP
Strategy (F188)	M8B2-14C309-AA

SODL-Side Obstacle Detection Control Module - Left

Newer than reflash database

Part	Part number		Part number
Assembly (F112)	Unknown	->	L8B2-14D455-BP
Assembly (F113)	L8B2-14F152-BN	->	None
Calibration (F124)	L8B2-14D564-BR	->	None
Calibration (F125)	L663-Standard-ST-RS:	->	None
Calibration F121	L8B2-14D370-BD		
Hardware (F111)	L8B2-14D366-BD		
Serial	1874342211800651		
Strategy (F188)	L8B2-14D368-BP	->	L8B2-14D368-BN
VIN	SALEA*****		

SODR-Side Obstacle Detection Control Module - Right

Newer than reflash database

Part	Part number		Part number
Assembly (F112)	Unknown	->	L8B2-14C689-BP
Assembly (F113)	L8B2-14F152-BN	->	None
Calibration (F124)	L8B2-14D564-BR	->	None
Calibration (F125)	L663-Standard-ST-RS:	->	None
Calibration F121	L8B2-14D370-BD		
Hardware (F111)	L8B2-14D366-BD		

Serial	1874342211800504		
Strategy (F188)	L8B2-14D368-BP	->	L8B2-14D368-BN
VIN	SALEA*****		

TCCM-Transfer Case Control Module

Latest Version

Part	Part number
Assembly (F112)	Unknown
Assembly (F113)	M8E2-7J426-AC
Calibration (F124)	M8E2-14C367-AL
Hardware (F111)	M8E2-14C365-AC
Serial	223450456
Strategy (F188)	M8E2-14C366-AL
VIN	SALEA*****

TCM-Transmission Control Module

Newer than reflash database

Part	Part number		Part number
Assembly (F113)	PY42-7000-AC	->	N8B2-7Z369-GAA
Hardware (F111)	M8E2-14C247-AA		
Serial	01102800082051		
Strategy (F188)	N8B2-7J104-GAC	->	N8B2-7J104-GAA
VIN	SALEA*****		

WDCM-Wireless Device Charger Module

Latest Version

Part	Part number
Assembly (F112)	Unknown
Assembly (F113)	L8B2-14E288-AE
Hardware (F111)	L8B2-14E287-AB
Serial	2159W72JHLSZ4702
Strategy (F188)	L8B2-14E282-AE
VIN	SALEA*****